

Repair Catalog

AUTOMOTIVE INSTRUMENT REPAIR SPECIALISTS

3 / 10 O'Connor Way, Wangara, WA, 6065
speedlineinstruments@bigpond.com
www.speedlineinstruments.com
Tel: 08 9409 3678



gauge specialists



Audi Repairs

AUDI TT INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Temperature and / or fuel guage faulty
- Flickering cluster
- Cluster/software programming

AUDI A6/S6/ALLROAD INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Temperature and / or fuel guage faulty
- Flickering cluster
- Cluster/software programming

AUDI A3/S3 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Temperature and / or fuel guage faulty
- Flickering cluster
- Cluster/software programming

AUDI A3/S3 BOSCH 5.3 ABS MODULE REPAIR



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Speedo not working
- Various faults

AUDI Q7 IINSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Gauge failure
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

AUDI S4 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination, flickering cluster
- Gauge failure
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

Audi Repairs

AUDI 80 INSTRUMENT CLUSTER REPAIR



- Odometer not working
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Temperature and / or fuel gauge faulty

AUDI A4 INSTRUMENT CLUSTER REPAIR



- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Flickering cluster
- Cluster/software programming

AUDI A6/S6 ABS MODULE REPAIR



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Speedo not working
- Various faults

AUDI A6/S6/ALLROAD INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Gauge failure
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

AUDI A3 INSTRUMENT CLUSTER REPAIR



- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Flickering cluster
- Cluster/software programming

AUDI A4 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination, flickering cluster
- Gauge failure
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW Repairs

BMW E39 /E38/E53 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW E36 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW E39 /E38/E53 MID REPAIR



- Lcd failure
- Illumination

BMW E30/E28



- Odometer failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Warning light repair
- Battery failure

BMW E36 OBC 18 BUTTON REPAIR



- Lcd failure
- Illumination repair

BMW E36 ACC UNIT REPAIR



- Lcd failure
- Illumination
- Intermittent power failure
- Unresponsive controls ie: blowing hot or cold air constantly
- Complete power failure

BMW Repairs

BMW E60 INSTRUMENT CLUSTER REPAIR



- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW E46 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Faulty Speedo/Tacho
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW E39 BOSCH ABS REPAIR



- ABS light warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Speedometer not working

BMW E36 OBC 8 BUTTON REPAIR



- Lcd failure
- Illumination repair

BMW E34 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Warning Light failure
- Cluster/software programming

BMW E85 / Z4 INSTRUMENT CLUSTER REPAIR



- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Speedometer / Tacho failure
- Cluster/software programming

BMW Repairs

BMW E90 PROFESSIONAL STEREO LCD REPAIR



- Illumination
- LCD Repair

BMW E46 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Faulty Speedo/Tacho
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Pointer/needle failure
- Cluster/software programming

BMW E39 BOSCH ABS REPAIR



- ABS light warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Speedometer not working

BMW E36 OBC 8 BUTTON REPAIR



- Lcd failure
- Illumination repair

BMW E34 INSTRUMENT CLUSTER REPAIR



- Lcd failure
- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Warning Light failure
- Cluster/software programming

BMW E85 / Z4 INSTRUMENT CLUSTER REPAIR



- Illumination
- Custom dials
- km/h or mph conversions
- Intermittent or complete cluster failure
- Speedometer / Tacho failure
- Cluster/software programming

Ford Repairs

FORD COURIER REPAIR



- Temp and Fuel gauge fault
- Intermittent or complete cluster failure
- Cluster/software programming

FORD FOCUS REPAIR



- Illumination
- LCD repair
- Incorrect warning lights
- Flickers on and off
- Intermittent or complete cluster failure
- Cluster/software programming

FORD EB CLUSTER REPAIR



- Odometer failure
- Speedometer repair
- Tachometer repair / calibration

FORD AU CLIMATE CONTROL REPAIR



- Illumination
- LCD repair

FORD TRANSIT BOSCH 5.7 ABS REPAIR



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Various faults

FORD TRANSIT INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Incorrect warning lights
- Flickers on and off
- Intermittent or complete cluster failure
- Cluster/software programming

Holden Repairs

HOLDEN ASTRA CLUSTER REPAIR



- Illumination
- LCD repair
- Flickers on and off
- Intermittent or complete cluster failure
- Cluster/software programming

HOLDEN VY/VZ LCD REPAIR



- Illumination
- LCD BLACK OR BLANK
- Cluster/software programming

HOLDEN VN/VP CLUSTER REPAIR



- Odometer failure
- Speedometer repair
- Tachometer repair
- Temp and fuel gauge repair

HOLDEN VZ CLUSTER REPAIR



- Illumination
- Complete cluster failure
- Cluster/software programming

HOLDEN BOSCH 5.7 ABS REPAIR



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Various faults

HOLDEN VN - VS INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Speedometer and Tachometer repair
- Intermittent or complete cluster failure
- Cluster/software programming

Holden Repairs

HOLDEN VECTRA CLUSTER REPAIR



- Illumination
- LCD repair
- Flickers on and off
- Intermittent or complete cluster failure
- Cluster/software programming

HOLDEN VY/VZ LCD REPAIR



- Illumination
- Pointer Failure with all other functions operating
- Cluster/software programming

Mercedes Benz Repairs

MERCEDES W220 CLUSTER REPAIR



- Partial or complete illumination repair
- Speedometer failure
- Buzzer failure
- LCD repair
- Complete power failure
- Cluster / software programming

MERCEDES W208 CLK CLUSTER REPAIR



- Illumination
- LCD Temp and Clock Pixel failure
- Centre display LCD
- Intermittant jumpy gauges
- Cluster/software programming

MERCEDES W124 INSTRUMENT CLUSTER REPAIR



- Odometer failure
- Speedometer repair
- Tachometer repair
- Time Clock repair
- Temp and fuel gauge repair

MERCEDES W140 INSTRUMENT CLUSTER REPAIR



- Illumination
- Odometer repair
- Complete cluster failure

MERCEDES W209 INSTRUMENT CLUSTER REPAIR



- Centre LCD repair
- Speedometer repair
- Intermittant gauges
- Complete cluster failure
- Illumination failure
- Cluster software programming

MERCEDES VITO INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Speedometer and Tachometer repair
- Intermittent or complete cluster failure
- Cluster/software programming

Mercedes Benz Repairs

MERCEDES W210 CLUSTER REPAIR



- Partial or complete illumination repair
- Speedometer failure
- Buzzer failure
- LCD repair
- Complete power failure
- Cluster / software programming

MERCEDES W208 CLK CLUSTER REPAIR



- Illumination
- LCD Temp and Clock Pixel failure
- Centre display LCD
- Intermittant jumpy gauges
- Cluster/software programming

MERCEDES W211 E CLASS INSTRUMENT CLUSTER REPAIR



- Centre LCD repair
- Speedometer repair
- Intermittant gauges
- Complete cluster failure
- Illumination failure
- Cluster software programming

MERCEDES W215 CL INSTRUMENT CLUSTER REPAIR



- Partial or complete illumination repair
- Speedometer failure
- Buzzer failure
- LCD repair
- Complete power failure
- Cluster / software programming

MERCEDES W463 INSTRUMENT CLUSTER REPAIR PRE FACE LIFT



- Partial or complete illumination repair
- Speedometer failure
- Buzzer failure
- LCD repair
- Complete power failure
- Cluster / software programming

MERCEDES W210 ACC REPAIR



- Illumination
- LCD repair
- Button failure

SAAB Repairs

SAAB GM 900 SID UNIT REPAIR



- Lcd failure
- Illumination
- Speaker failure

SAAB GM 900 ACC UNIT REPAIR



- Lcd failure
- Illumination

SAAB 93 ACC UNIT REPAIR



- Lcd failure
- Illumination

SAAB 93 SID 1 REPAIR



- Lcd failure
- Illumination
- Speaker failure

SAAB 5.4 ABS MODULE REPAIR



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Various faults

SAAB 93 SID 2 REPAIR



- Lcd failure
- Illumination
- Speaker failure

SAAB Repairs

SAAB 95 SID 1 REPAIR



- Lcd failure
- Illumination
- Speaker failure

SAAB 95 SID 2 REPAIR



- Lcd failure
- Illumination
- Speaker failure

SAAB ABS REPAIR WITH TRACTION



- ABS warning on cluster
- No comms via diagnostic testing
- Sensor faults
- Various faults

SAAB 9-5 INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Intermittent or complete cluster failure
- Cluster/software programming

SAAB 9-3 INSTRUMENT CLUSTER REPAIR



- Illumination
- LCD repair
- Intermittent or complete cluster failure
- Cluster/software programming

Custom Dials & Conversions

CUSTOM PRESSURE GAUGE



DUCATTI MPH EXPORT CONVERSION



REFURBISHED DIALS



VDO WHITE FACE DIALS



CUSTOMISED DIALS



MPH - KM/H CONVERSIONS



COLOUR CONVERSIONS



HARLEY DAVIDSON MILES - KMS



Custom Dials & Conversions

HARLEY DAVIDSON CUSTOM
DIAL



MILES - KM/H CONVERSION



TACHOMETER CONVERSIONS



CLASSIC CONVERSIONS



PORSCHE CONVERSIONS



COLOUR CONVERSIONS



ELECTRONIC CONVERSIONS



CHEV RESTORATION

